

The diagram illustrates a mechanical assembly. On the left, a motor (2) is connected to a shaft (5). The shaft (5) is part of a mechanism (3) that includes a lever (11) and a roller (6). A motor (10) is also connected to the lever (11). A separate component (4) is shown on the right, which is a rectangular housing. Inside this housing, there is a shaft (27) that passes through a series of components: a block (28), a roller (24), a lever (26), and a roller (25). The roller (25) is in contact with a surface (12a) and has a width (W) indicated. The entire assembly is shown in a cross-sectional view.




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG. 10A




FIG. 10B




FIG. 11




FIG. 12




FIG. 13




FIG. 14

